

IQAN software update information:

MD3 recommended software version

Recommended version: **IQANdesign 2.63 or later**
 IQANdesign 3.15 or later

Summary:

- IQAN-MD3-M15 (part 20077793) is an updated hardware version of the MD3 that requires a new software.
- The previous version IQAN-MD3 (part 20072409) may also need new software. Modules with this part number produced after 2014 week 20 can have problems with the display if using older SW version.

Recommended Action:

We recommend all users of the IQAN-MD3 (part number 20077793 and 20072409) **manufactured after 2014 week 20** to update to:

IQANdesign 2.63 or later
IQANdesign 3.15 or later

(Use IQANdesign->Help->Check For Updates to get the latest IQANdesign version)

Detailed description:

IQAN-MD3-M15 (part 20077793)

Support for this hardware was introduced in IQANdesign 3.15 (and in IQANdesign 2.62). Older versions cannot be loaded to the module.

IQAN-MD3 modules (part 20072409) built *after* w1420

Requires a different power-on sequence for the display element, implemented in IQANdesign 3.14 and IQANdesign 2.61. With older SW versions, the display element may not start in elevated temperatures.

Earlier information about bios update to 1.04 as the solution was misleading, these module need both bios 1.04 *and* SW version 2.61, 2.63, 3.14 or later to avoid the problem.

The display on these modules *do not* work with IQANdesign 2.62

IQAN-MD3 modules (part 20072409) built *before* w1420

These module may use any version.